

HARPER COUNTY ROAD & BRIDGE
Weekly County Commission Report
March 7-11, 2016

KENT STONEBRAKER-EAST FOREMAN

1. Excavator 635 removing x-pipe on Rd 751-B. Trucks 305 & 310 hauling shale to field entrance on Rd 670-23. Truck 217 to J&K Diesel for repairs. Bucket Truck 613 with Chipper 690 trimming trees along Rd 744-H. Dozer 627 ripping shale at Plumb Thicket Landfill. Graders patrolling.
2. Installed 5 floor boards at Bridge 755-AA. Dozer 627 ripping shale at Plumb Thicket Landfill. Worked on Grader's 256 & 255. Worked on barricades.
3. Mounted 2 new tires on the front of Grader 257. Work on barricades. Built rack to store 4x4 posts at Danville Shop. Trimmed trees on Rd 739-A. Reset stop sign on Rd 739-A, north end. Reset speed limit sign on Rd 662-22. Graders patrolling.
4. Installed new floor boards & hub rails at Bridge 755-AA. Replaced damaged running boards at Bridge 735-F. Graders patrolling.
5. Trucks 305, 310 & 606 hauling sand to Rd 684-25 & 741-B. Dozer 627 ripping shale at Plumb Thicket Landfill. Graders patrolling.

JIM THOMPSON-SHOP FOREMAN

1. #216 2006 Sterling Truck, repairs to engine. #632 CAT Excavator, sos motor. #154 CAT 120M Grader, sos motor.
2. #216 2006 Sterling Truck, installed engine, hookup etc.
3. #216 2006 Sterling Truck, finished hookup on engine & started.
4. #216 2006 Sterling Truck, replaced bad wiring harness & let engine run to check over & finished up repairs.
5. #216 2006 Sterling Truck, worked on rear wheel seal leak.

LAWRENCE SMITH-WEST FOREMAN

Cleaned blow sand out of ditch on Rd 686-3 & put on Rd's 713-O & P & 688-2. Graders patrolling, spreading shale & sand. Excavator 632 helping Bridge Crew rebuild west bulk head at Bridge 674-9 #2. Dozer 628 pushing up & stockpiling gravel at Jacobs Pit. Reset downed signs on Rd's 690-2, 664-12, 733-B & intersection of SW 80 Ave & SW 70 Rd.

JEFF NULIK-BRIDGE FOREMAN

1. Moved materials to Bridge 674-9 #2. Removed guardrails, hub rails & decking from west span at Bridge 674-9 #2.
2. Jump started Crane 401. Repaired/replaced low beam headlights on 681. Unmounted 734 Welder from 734 for repairs at Anderson Welding. Made shims for Grader 255 mold board extensions.
3. Moved Crane 401 to Bridge 674-9 #2.
4. Removed stringers & dug out abutment & wing walls at Bridge 674-9 #2. Put boom on crane.
5. Moved piling to Bridge 674-9 #2. Threaded cables & made repairs to boom on crane.